

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
MONT,
32-MILTO,
1-

HAER No. MT-43

Milltown Dam
On the Clark Fork River
Town of Milltown
Missoula County
Montana

Paul Anderson, Photographer, May 1988

- MT-43-1 GENERAL VIEW OF DAM, POWERHOUSE AND CAMP TO SOUTHWEST
- MT-43-2 VIEW OF DAM FROM WEST BANK OF RIVER TO NORTH
- MT-43-3 DAM AND POWERHOUSE COMPLEX WITH CAMP IN BACKGROUND TO NORTHEAST
- MT-43-4 DAM SPILLWAY AND POWERHOUSE FROM DOWNRIVER, VIEW TO SOUTHEAST
- MT-43-5 Photographic copy of photograph (July 7, 1930, original print in possession of Montana Power Company, Butte, Montana). AERIAL VIEW OF DAM SITE TO SOUTHEAST
- MT-43-6 Photographic copy of photograph (May 31, 1909, original print in possession of Montana Power Company, Butte, Montana). VIEW OF DAM FROM DOWNSTREAM DURING FLOOD.
- MT-43-7 Photographic copy of photograph (September 20, 1908, original print in possession of Montana Power Company, Butte, Montana). "MIXING CONCRETE FOR LOWER COFFER DAM"
- MT-43-8 Photographic copy of photograph (October 29, 1908, original print in possession of Montana Power Company, Butte, Montana). "PROGRESS ON BREAKWATER CONSTRUCTION"
- MT-43-9 Photographic copy of photograph (February 8, 1908, original print in possession of Montana Power Company, Butte, Montana). "PROGRESS WORK AT TOE OF DAM"
- MT-43-10 Photographic copy of photograph (January 23, 1909, original print in possession of Montana Power Company, Butte, Montana). "GENERAL VIEW OF WORK IN BREAK SHOWING CONSTRUCTION OF TIMBER BENTS BEHIND CONCRETE DAM AND WORK OF CONCRETING 24 FT CRIB TO ROCK CLIFF"

- MT-43-11 Photographic copy of photograph (February 24, 1909, original print in possession of Montana Power Company, Butte, Montana). "GENERAL VIEW OF RECONSTRUCTION WORK NOTE CONCRETE TIE BETWEEN SECTIONS OF 8 FT & 24 FT CRIBS"
- MT-43-12 Photographic copy of photograph (March 17, 1909, original print in possession of Montana Power Company, Butte, Montana). "TIMBER WORK IN BREAK BEHIND MAIN CONCRETE DAM"
- MT-43-13 Photographic copy of photograph (March 23, 1909, original print in possession of Montana Power Company, Butte, Montana). "DRIVING THE LAST #85 RAIL"
- MT-43-14 Photographic copy of photograph (April 10, 1909, original print in possession of Montana Power Company, Butte, Montana). "COMPLETING FILL IN CRIBWORKS END OF DAM"
- MT-43-15 Photographic copy of photograph (ca. April 1909, original print in possession of Montana Power Company, Butte, Montana). VIEW OF POWERHOUSE AND WORK ON BREAKWATER
- MT-43-16 Photographic copy of photograph (April 20, 1909, original print in possession of Montana Power Company, Butte, Montana). "PROGRESS WORK ON SOUTH ABUTMENT"
- MT-43-17 Photographic copy of photograph (April 22, 1909, original print in possession of Montana Power Company, Butte, Montana). "PLACING RIP RAP"
- MT-43-18 Photographic copy of photograph of reconstruction drawings (March 6, 1909, original print in possession of Montana Power Company, Butte, Montana). "SECTION THRU BREAK AT SOUTH END OF DAM SHOWING DETAILS OF RECONSTRUCTION"
- MT-43-19 Photographic copy of photograph of reconstruction drawing (March 6, 1909, original print in possession of Montana Power Company, Butte, Montana). "PLAN AND DOWNSTREAM ELEVATION OF RECONSTRUCTION WORK"

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HAER MT-43

MILLTOWN DAM

Clark Fork River, 6 miles upstream from Missoula

Milltown

Missoula County

Montana

Photographs HAER MT-43-1 through HAER MT-43-19 were previously transmitted to Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Kristi Hager, photographer, March 2007

MT-43-20	Long view of dam with trash boom, view to north
MT-43-21	3/4 view of dam, view to west
MT-43-22	southeast elevation, dam, view to northwest
MT-43-23	3/4 view of dam, view to north

INDEX TO COLOR TRANSPARENCIES

Kristi Hager, photographer, March 2007

MT-43-24 (CT)	Long view of dam, view to south
---------------	---------------------------------